

Copy Tapes sent to MR Mc Laughlin



14/9/48

BRITISH INFORMATION SERVICES

(OFFICE OF THE U. K. HIGH COMMISSIONER IN PAKISTAN)

HERMAN & MOHATTA BUILDINGS

WOOD STREET

P. O. BOX 212

KARACHI

TELEGRAMS: "BRITINFORM"

REF. K/502.

P.A.

TELEPHONES:

DIRECTOR - - - - - 2187
EDITOR-IN-CHIEF - - 328Z
REGIONAL INFORMATION OFFICER - 2702

4039

8th September 1948.

My dear Crawley,

Attached are three sample tapes of "Hell" which I would like you to pass on to the G.P.O. for their comments.

Sample No.1. was taken from George Peter Victor on the 10 M/cs channel at 0230 hours G.M.T. September 8th. No amount of adjustment would improve the printing.

Without any alteration to the equipment sample No.2. was taken at 0615 hours G.M.T. from the L.P.S. transmission on Mike Ink Charlie on 18 M/cs. As you will see the printing is quite good. Sample No.3 was taken from George Beer Robert at 0620 hours G.M.T. and is also good.

It is hard to believe the fault with sample number one lies in our equipment in view of the fact all other transmissions are quite good including "Tass" etc. However, knowing the G.P.O. they are not likely to put out a poor transmission.

A guide may be that earlier in the year when we were receiving the test transmissions on the 13 M/cs channel I reported to MacLoughlin that printing was poor. Is it at all possible that reception conditions could cause this poor printing. I must admit I cannot see why conditions should effect the printing.

Another small point. The sample tape No. 1 appears to be well over inked.

Samples two and three do not give this impression. As the tapes were a direct follow on it is hardly likely the inking pad would have dried up so quickly. I believe I will find that with the same

G.F. Crawley Esq,
Information Dept,
C.R.O. Downing Street, S.W.I.

/inking

16/11

BRITISH INFORMATION SERVICES

OFFICE OF THE U. K. HIGH COMMISSIONER IN PAKISTAN
GERMAN & WOLFF BUILDINGS
WOOD STREET
P. O. BOX 212
KARACHI

RECEIVED
INFORMATION
SECTION
16/11/52

-2-

inking pad the transmission tomorrow on 10 M/cs will also appear to be over inked.

The number of errors in transmissions appears to be on the increase and with our Pakistan typists, missing letters cause them a little trouble. It might be a good idea if you saw a sample tape of a complete transmission.

Yours sincerely,

Kenneth Jewers

(Kenneth Jewers)
Director.

P.S. Sample tape No.4 complete tape also enclosed, you will appreciate that samples 1,2 and 3 were received in that order. Since writing the above letter I have received George Victor Percy on September 9th and without Copy to: changing the inking pad you will see that sample 4 still The Director, shows signs of over inking.

B.I.S.
New Delhi.

Another small point. The sample tape No. 1 appears to be well over inked.

Samples two and three do not give this impression. As the tapes were a direct follow on it is hardly likely the inking pad would have dried up so quickly. I believe I will find that with the same

G. F. Crawley had
Information Dept.
C. S. D. Downing Street, S.W. 1.